



**Federal Communications Commission**  
**Public Safety and Homeland Security Bureau**  
**1270 Fairfield Road**  
**Gettysburg, PA 17325-7245**

**CONSTRUCTION/COVERAGE DEADLINE**  
**NOTICE OF LICENSE TERMINATION PENDING STATUS**

ATTN: AGTE. ELIEZER GOMEZ ROSA  
PUERTO RISO STATE POLICE  
12505 PARK POTOMAC AVE., 6TH FLOOR  
PO BOX 70166  
SAN JUAN, PR 00936-8166

Date: 05/14/2014  
Reference Number: 5789966  
Radio Service: YE  
Call Sign: WQRB369

Re: PUERTO RICO STATE POLICE

The below-referenced license was granted authorizing the construction and operation of a new geographically based system; a new system for one or more new transmitter sites; or a modification to add one or more new transmitter sites to the existing license and/or add frequencies to one or more existing locations or microwave paths already authorized under the license. Granting this license imposed a construction or coverage requirement deadline on that system, location, and/or frequency. For more information on construction and coverage requirements, visit website at <http://wireless.fcc.gov/licensing/const-req/>.

Our records indicate, however, that we have not received the Required Notification of Construction, due within 15 days after the construction or coverage requirement deadline, 47 C.F.R. § 1.946(d), or a Request for an Extension of Time, due before the expiration of the construction or coverage requirement deadline, id. 1.946(e), for this license. If a licensee does not file the Required Notification or Extension of Time request, we presume that the license or license component has not been constructed, or the coverage requirement has not been met. As a result, the Commission's Universal Licensing System (ULS) has placed the below-referenced license or license component in "Termination Pending" status. A Weekly Termination Pending Public Notice was recently issued listing the license in termination pending status. If the licensee met its construction or coverage requirement, it has 30 days from the date of the Public Notice to file a petition for reconsideration, as described more fully below, showing that it timely met the construction or coverage deadline. Grant of a timely petition will result in removal of the "Termination Pending" status and the license or license component will be returned to "Active" status. Once the 30-day reconsideration period has closed and if the licensee has not filed a petition for reconsideration showing that it timely met the construction or coverage requirement, the "Termination Pending" status in ULS will change to "Terminated," effective as of the construction or coverage requirement deadline on its license. The spectrum will then be available to the Commission for reassignment by competitive bidding or other means, according to the rules of the wireless service.

In filing its petition for reconsideration, the licensee must include the actual date when construction was completed or the coverage requirement was met. Petitions for Reconsideration may be filed electronically through ULS or by paper through the Office of the Secretary. To file electronically, visit the ULS website at <http://wireless.fcc.gov/uls/>. Under "ULS Online Systems", click on "Submit a Pleading", complete the administrative information, and upload your Petition for Reconsideration. If filing by paper, the petition for reconsideration should state, on the first page: "To: Public Safety and Homeland Security Bureau, Policy Division, Call Sign WQRB369 and Radio Service YE." For further information on filing a petition for reconsideration, visit the Commission's website at <http://wireless.fcc.gov/rules.html> and select "Part 1 – Practice and Procedure." The rules for petitions for reconsideration can be found at Section 1.106, 47 C.F.R. § 1.106. For filing addresses, visit the Office of the Secretary's website at [www.fcc.gov/osec](http://www.fcc.gov/osec).

For additional information or assistance, you may visit the website at <http://esupport.fcc.gov>. You may also call the FCC Support Center at (877) 480-3201 (TTY 717-338-2824). To provide quality service and ensure security, all telephone calls are recorded.

| Call Sign | Radio Service | ULS Loc/Path# | Antenna# | Frequency Lower | Frequency Upper | Construction Deadline |
|-----------|---------------|---------------|----------|-----------------|-----------------|-----------------------|
| WQRB369   | YE            | 1             | 1        | 851.30000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 1             | 1        | 851.80000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 1             | 1        | 852.30000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 1             | 1        | 853.30000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 2             | 1        | 851.38750000    |                 | 04/09/2014            |
| WQRB369   | YE            | 2             | 1        | 851.91250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 2             | 1        | 852.41250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 2             | 1        | 853.38750000    |                 | 04/09/2014            |
| WQRB369   | YE            | 2             | 1        | 856.16250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 3             | 1        | 851.06250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 3             | 1        | 853.06250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 3             | 1        | 853.55000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 3             | 1        | 853.82500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 851.01250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 851.35000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 851.65000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 851.96250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 852.27500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 852.57500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 4             | 1        | 854.81250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 851.10000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 851.46250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 851.77500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 852.40000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 852.71250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 853.01250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 5             | 1        | 853.32500000    |                 | 04/09/2014            |

For additional information or assistance, you may visit the website at <http://esupport.fcc.gov>. You may also call the FCC Support Center at (877) 480-3201 (TTY 717-338-2824). To provide quality service and ensure security, all telephone calls are recorded.

| Call Sign | Radio Service | ULS Loc/Path# | Antenna# | Frequency Lower | Frequency Upper | Construction Deadline |
|-----------|---------------|---------------|----------|-----------------|-----------------|-----------------------|
| WQRB369   | YE            | 6             | 1        | 806.01250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.06250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.10000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.30000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.35000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.38750000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.46250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.65000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.77500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.80000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.91250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 806.96250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 807.27500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 807.30000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 807.40000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 807.41250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 807.57500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 807.71250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.01250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.06250000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.30000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.32500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.38750000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.55000000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 808.82500000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 809.38750000    |                 | 04/09/2014            |
| WQRB369   | YE            | 6             | 1        | 809.81250000    |                 | 04/09/2014            |

For additional information or assistance, you may visit the website at <http://esupport.fcc.gov>. You may also call the FCC Support Center at (877) 480-3201 (TTY 717-338-2824). To provide quality service and ensure security, all telephone calls are recorded.

| Call Sign | Radio Service | ULS Loc/Path# | Antenna# | Frequency Lower | Frequency Upper | Construction Deadline |
|-----------|---------------|---------------|----------|-----------------|-----------------|-----------------------|
| WQRB369   | YE            | 6             | 1        | 811.16250000    |                 | 04/09/2014            |